Invoice No. :17/BR/21011482

Customer Name & Address :



Labour Charges

Date :31/12/2021 13:44:53

Job Card Date :30/12/2021 Mileage :67400

> EW Type :NA MCP No. :

Last Service :07-11-20

Tax Paid Amount

0.00 CUS

Next Service Due : PMS80

Taxable Amount

317.79

71.87

81.24

9.36

186.44

40.64

86.40

605.93

1597 28

SA(M):9152001302

SUMIT A AWASTHI Job Card No :JC21013229 SA Name :KARAN DEEPAK DONDILKAR Pin : 410210 State & Code : 27-MAHARASHTRA Model :S-CROSS (D13) Ch Mobile Loyalty Card :77000007379 Fuel Trim : Service type :PAID SERVICE Cust GSTIN/UIN :GSTUNREGISTERED Place of Supply:MAHARASHTRA Srl. Part Number Description Batch HSN/SAC Тах Qty. Rate Parts Demanded Repairs-Others/Suggested Jobs 18% 16510M86J20 ELEMENT OIL FILTER 84212300 1.000 1 AC 317.79 2 16590M86J30 PLUG ASSY, OIL DRAIN AC 84099113 28% 1 000 71 87 43228M79G10 3 WEIGHT, WHEEL BALANCE (40GRAM) AD 87087000 2.000 40.62 28% 4 87418M84020 DOOR GUARD AA 87089900 28% 4.000 2.34 5 HINGE RELIEF WAX 99000M24121-085 AB 34031900 18% 1.000 186.44 6 99000M25010 GREAS SATCHET, FR CALIPER SLIDING PI 34039900 18% 4.000 AA 10.16 7 990J0M999H2-260 SCREEN WASH 50 AB 87089900 18% 6.000 14 40 8 990J0M999H2-640 ECSTAR AC DISINFECTANT AB 87089900 18% 1.000 605.93 99999MN5W30-IOC 9 ECSTAR NEXA 5W30 DIESEL - IOC AC 27101980 18% 3.200 499 15 Labour Demanded Repairs-Others/Suggested Jobs

ID: 1517187279

1	ZE20L0	CLUTCH BLEEDING	998729	CUS	450.00
2	ZE23L0D	PMS - 1D 20K/40K/50K/70K/80K/100K/110K	998729	CUS	2995.00
3	ZZ07H	HYGIENE CHARGE	998729	CUS	200.00
4	ZA12L0	TYRE ROTATION	998729	CUS	0.00
5	ZA72L0	ACCESSORIES FITMENT / REPAIRS	998729	CUS	400.00
6	ZA12L1	SIDE SLIP & BRAKE TESTER CHARGES	998729	CUS	1250.00
7	DE10R0	INTER COOLER	998729	CUS	668.00
8	ZA05L0	WHEEL BALANCING - 5 WHEEL	998729	CUS	785.00
9	ZA11L0	WHEEL ALIGNMENT	998729	CUS	920.00
10	ZA80L0	ALL LIGHTS CHECK UP	998729	CUS	250.00
11	ZF01L0	BUMPER CHECK/ FIX UP/ ADJUST	998729	CUS	532.00

Recommendations :	Sub Total Amount	:	2996.95	8450.00	0.00
INDICATOR SIRON NOT WORKING, FRONT BOTH WIPER	Less Discount	:	149.84	449.25	0.00
ADE CUT NEED TO BE REPLACE, CLUSTER METER EED TO BE REPLACE DUE TO SIDE INDICATIOR BEEP & EAT WARNING ALARM NOT WORKING DICKY SHOCKUP	CGST @ 14%	:	21.61		
	SGST @ 14%	:	21.61		
NEED TO BE REPLACE, REAR SHOCKUP NEED TO BE REPLACE , 5% PARTS & 15% PMS LABOUR DISCOUNT AS	CGST @ 9%	:	242.35	720.07	
PER SMRE, BODY POLISH & INTERIOR CLEANING	SGST @ 9%	:	242.35	720.07	
COMENDED TO CUSTOMER , CUSTOMER NOT GIVEN PROVAL	Sub Total Amount	:	3375.03	9440.89	0.00
	MCP Adjustment Amount	:			0.00
	Net Bill Amount (Rounded)	:			12816.00

Rupees Twelve Thousand Eight Hundred And Sixteen Only

\* Unapproved fitments affects the performance Suggested to keep the vehicle in original specifications.

For SHIVAM AUTOZONE INDIA PVT. LTD.

Authorised Signatory

Dealer GSTIN : 27AAPCS4402A1ZN

vehicle

I acknowledge that the jobs/repairs/service carried out in my vehicle and the respective cost estimates were explained to me. I have received my vehicle after completion of all repairs being carried out to my satisfaction and I confirm that my vehicle is in good

condition. I further authorize this workshop to contact me by call or sms to inform me with any other information in relation to my

Customer Signature

Mobile No.:

Gate Pass								
GP No. : GP21012569 Cust. Name :SUMIT A AWASTHI	Date : 31-12-2021 13:44:53 Model : S-CROSS (D13)	Job Card No.: JC21013229	Bill.No. BR/21011482	Bill Date : 31-12-2021 13:44:53	Amount 12816.00			
Just. Name :SUMITA AWASTHI Fech. Name :ADITYA UDAY KHOT		0021010220	51021011402					

**Customer Signature** 

Accountant Signature



Created By : KARAN DEEPAK DONDILKAR