

THE PLAY/THE GAP LEFT IN THE FIXING OF THE BOLT LED TO THE VIBRATION OF THE HARDENED RUBBER BUSH WHICH BRUSHED AGAINST THE BOLT CAUSING WEAR & TEAR (SHEARING) OF THE BOLT. EVENTUALLY, THE BOLT CRACKED.

