(~)ebasto

Feel the drive

Sunroof: Doc.-No.:


Date:

Hollandia 300, 500, 600, 700, 710 0912033A

20-04-2004

3. Operating full electronic versions

3.1. Programming the sunroof before using it the first time




(ebasto

Sunroof: Doc.-No.:


Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004

3. 2. Opening of the sunroof




Opening sunroof into sliding position:

With ignition switched on, press \blacktriangle -button shortly.




Press ▲-button shortly again when glass panel reached desired position.



Opening of sunroof in max. tilt position:

With ignition on, press open button continuously, release button when panel is in max. tilt position.



By pressing button \triangle or ∇ continuously, panel is adjustable in 4 different positions. When button is released, roof remains in momentary position.


(ebasto

Sunroof: Doc.-No.:

Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004

3.3. Closing of sunroof






Sunroof: Doc.-No.:

Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004


3.4. Programming two pre-set positions



Place panel in first favoured position.

Press **①**-button for three seconds to store this position under **①**-button.


A beep will confirm programming.



Place panel in second desired position.

Press **2**-button for three seconds to store this position under **2**-button.

Beep will confirm programming.



Press button **1** or **2** to open panel to favoured positions.

Repeat steps for programming new pre-set positions.

(~)ebasto


Feel the drive

Sunroof: Doc.-No.:

Date:


Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004

3.5. Auto close




Switch off ignition.

Sunroof beeps once to indicate that panel closes after three seconds.



Panel closes. You hear 2 beeps.




For preventing roof from closing automatically, press ▲-button briefly within 3 seconds after switching off ignition.

(ebasto


Sunroof: Doc.-No.: Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004


3.6. Jamming protection



When closing sunroof......



......sunroof opens automatically when panel encounters an obstacle.



When obstacle is removed, panel will close again.

Jamming protection can be switched off by operating button continuously even when ignition is off.



Do not leave children unattended in your car!



Sunroof: Doc.-No.:


Date:

Hollandia 300, 500, 600, 700, 710 0912033A


20-04-2004

4. Annotations for electric and full electronic versions

4.1. Operation of sunshade




Sunshade can be placed in every position.





Do not close sunshade completely at >50 km/h and open sunroof (vibrations!). Leave gap of >3cm.




(~)ebasto

Sunroof: Doc.-No.: Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004

4.2. Special notes




(ebasto

Sunroof: Doc.-No.: Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004


4.3. Maintenance



Clean glass panel with glass cleaner.



Do not use scratching substances!



Clean rubber seal with wet cloth at least every half vear.

Apply talcum powder to seal to keep rubber flexible.




Do not use grease or oil!


(~)ebasto Feel the drive

Sunroof: \Doc.-No.: Date:


Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004



Check seal when sunroof leaks. Clean seal with a wet cloth. Apply talcum powder.



Contact your nearest Webasto-dealer for service, if sunroof still leaks.




(~)ebasto

Sunroof: Doc.-No.:


Date:

Hollandia 300, 500, 600, 700, 710 0912033A 20-04-2004

4.4. Malfunctioning




If sunroof does not work at all, check fuse.



Electronic sunroofs:

If sunroof is not working properly, re-program sunroof (see chapter 3.1).



Check again correct functioning of sunroof.



When sunroof is still not working properly, contact nearest Webasto dealer for service.