

P/L	Labor Code/Part#	Description	Issue Type	Qty	Job Value/ RILP	Disc /Item	Dis %	VAT/ S.Tax %	OC/VAT (WCT)%	Amount(₹)
CARRYOUT ACCIDENTAL REPAIRS										
L	ACDNTRPR	ACCIDENTAL REPAIR	Paid	1		0	0	15		0.00
P	71101T9DK00ZZ	FACE.FR BUMPER	Paid	1	2042.61	0	0	14.5		2338.79
P	71140T9AT00	UP BEAM R.FR BUMP	Paid	1	414.78	0	0	14.5		474.92
P	71190T9DK00	UP BEAM L.FR BUMP	Paid	1	427.83	0	0	14.5		489.87
P	71193T9DK00	SPACER R.FR BPR SIDE	Paid	1	96.52	0	0	14.5		110.52
P	71198T9DK00	SPACER L.FR BPR SIDE	Paid	1	96.52	0	0	14.5		110.52
P	91505TM8003	CLIP BUMPER	Paid	5	97.39	0	0	14.5		557.56
P	33100T9AK01	LIGHT ASSY R HEAD	Paid	1	4017.39	0	0	14.5		4599.91
P	33150T9AK01	LIGHT ASSY L HEAD	Paid	1	4086.96	0	0	14.5		4679.57
P	60100T9DK00ZZ	HOOD COMP	Paid	1	3693.91	0	0	14.5		4229.53
P	60120T9AT00ZZ	HINGE COMP R.HOOD	Paid	1	1351.3	0	0	14.5		1547.24
P	60170T9AT00ZZ	HINGE COMP L.HOOD	Paid	1	1351.3	0	0	14.5		1547.24
P	74218T9DK00	SET COWL TOP ASSY	Paid	1	888.7	0	0	14.5		1017.56
P	91501TR0003	CLIP INN FENDER	Paid	20	67.83	0	0	14.5		1553.31
P	73126SYY000	RUBBER B FRONT WINDSHIELD DAMPER	Paid	1	725.2	0	0	14.5		830.35
P	73127T9CK00	RUBBER.FR WSHLD D	Paid	2	28.36	0	0	14.5		64.94
P	73150T9CK01	MLDG.FR WSHLD UPR	Paid	1	151.3	0	0	14.5		173.24
P	91568TF0003	CLIP.FR WSHLD UPR	Paid	2	224.32	0	0	14.5		513.69
P	IA260165310	3M-SUPER FAST URETHANE CARTRIDGE 310 ML	Paid	3	1000	0	0	14.5		3435.00
P	73227T9AT00	RUBBER. WSHLD DAM	Paid	1	104.15	0	0	14.5		119.25
P	91501S70003	FASTENER. B WSHLD	Paid	2	76.52	0	0	14.5		175.23
P	91536SS0J01	FASTNER A WSHILD	Paid	2	69.57	0	0	14.5		159.32
P	91568TF0003	CLIP.FR WSHLD UPR	Paid	2	224.32	0	0	14.5		513.69
P	60210T9AT50ZZ	PANEL COMP R.FR F	Paid	1	1411.3	0	0	14.5		1615.94
P	60260T9AT50ZZ	PANEL COMP L.FR F	Paid	1	1411.3	0	0	14.5		1615.94
P	74150T9DK00	FENDER ASSY L.FR	Paid	1	470	0	0	14.5		538.15
P	76208T9CD21	SET RH-R.R/C DOOR	Paid	1	4083.35	0	0	14.5		4675.44
P	76258T9CD21	SET RH-L.R/C DOOR	Paid	1	4083.35	0	0	14.5		4675.44
P	76251T9CD21ZC	SKULLCAP L. S/T	Paid	1	242.61	0	0	14.5		277.79
P	76201T9CD21ZC	SKULLCAP R. S/T	Paid	1	242.61	0	0	14.5		277.79
P	76400T9CD01	MIRROR ASSY RR VI	Paid	1	571.3	0	0	14.5		654.14
P	83200T9DD21ZA	LINING ASSY ROOF (NORMAL)	Paid	1	2117.39	0	0	14.5		2424.41
P	83203T9DD00	PAD R.FR ROOF SID	Paid	1	93.04	0	0	14.5		106.53
P	83253T9DD00	PAD L.FR ROOF SID	Paid	1	93.04	0	0	14.5		106.53
P	83254T9DD00	PAD L.RR ROOF SID	Paid	1	38.9	0	0	14.5		44.54
P	83204T9DD00	PAD R.RR ROOF SID	Paid	1	38.9	0	0	14.5		44.54
P	84101T9AT01ZA	GARN ASSY R.FR PLR	Paid	1	237.39	0	0	14.5		271.81
P	84151T9AT01ZA	GARN ASSY L.FR PLR	Paid	1	237.39	0	0	14.5		271.81
P	04635T9DK00ZZ	PANEL R.FR OUTSID	Paid	1	33361.74	0	0	14.5		38199.19
P	04645T9DK00ZZ	PANEL L.FR OUTSID	Paid	1	33361.74	0	0	14.5		38199.19
P	04636T9DK00ZZ	PANEL SET R.RR OUTSIDE	Paid	1	35427.83	0	0	14.5		40564.87
P	76630T9AT01	BLADE.WSHLD WIPER	Paid	1	413	0	0	14.5		472.88
P	76620T9AT01	BLADE.WSHLD WIPER	Paid	1	434.7	0	0	14.5		497.73
P	67050T9CD00ZZ	PANEL COMP L.FR D	Paid	1	6006.96	0	0	14.5		6877.97
P	67366T9CD01	TAPE L FR DOOR SA	Paid	1	136.6	0	0	14.5		156.41

P/L	Labor Code/Part#	Description	Issue Type	Qty	Job Value/ RTLP	Disc /Item	Dis %	VAT/ S.Tax %	OC/VAT (WCT)%	Amount(₹)
P	73350T9CD00	GLASS ASSY L FR D	Paid	1	924.6	0	0	14.5		1058.67
P	72375T9AT01	WTHSTP L FR DOOR	Paid	1	324.35	0	0	14.5		371.38
P	83561T9DD21ZA	BASE COMP L FR DOOR	Paid	1	1047.83	0	0	14.5		1199.77
P	72275T9A003	RUNCHANNEL L FR D	Paid	1	576.3	0	0	14.5		659.86
P	63120T9AT00ZZ	STIFF COMP R FR P	Paid	1	3135.65	0	0	14.5		3590.32
P	67510T9CD00ZZ	PANEL COMP R RR D	Paid	1	14120	0	0	14.5		16167.40
P	67825T9CD01	TAPE R RR DOOR SA	Paid	1	115.9	0	0	14.5		132.71
P	73400T9AT00	GLASS ASSY R RR D	Paid	1	924.6	0	0	14.5		1058.67
P	72735T9A003	RUNCHANNEL R RR D	Paid	1	573.04	0	0	14.5		656.13
P	72335T9AT01	WTHSTP R FR DOOR	Paid	1	314.4	0	0	14.5		359.99
P	72835T9AT01	WTHSTP R RR DOOR	Paid	1	286.96	0	0	14.5		328.57
P	72875T9AT01	WTHSTP L RR DOOR	Paid	1	286.96	0	0	14.5		328.57
P	75800T9CD11ZC	MUD GUARD R FR	Paid	1	377.78	0	0	14.5		432.56
P	75810T9CD11ZC	MUD GUARD L FR	Paid	1	377.78	0	0	14.5		432.56
P	75820T9CD11ZC	MUD GUARD R RR	Paid	1	510.29	0	0	14.5		584.28
P	75830T9CD11ZC	MUD GUARD L RR	Paid	1	510.29	0	0	14.5		584.28
P	75495T9CD00	GARN ASSY L FR PL	Paid	1	138.5	0	0	14.5		158.58
P	74316T9CD01	MLDG ASSY L ROOF	Paid	1	341.2	0	0	14.5		390.67
P	72640T9CD21	HANDLE ASSY R RR	Paid	1	2113.26	0	0	14.5		2419.68
P	68500T9DK30ZZ	LID COMP TRUNK	Paid	1	4393.04	0	0	14.5		5030.03
P	75711T9CD00	EMBLEM RR HONDA	Paid	1	210.43	0	0	14.5		240.94
P	75722T9CD00	EMBLEM RR CAR NAM	Paid	1	210.43	0	0	14.5		240.94
P	75725T9DD00	EMBLEM RR I-DTEC	Paid	1	135.5	0	0	14.5		155.15
P	51611T9CT11	DAMPER UNIT R FR	Paid	1	2173.91	0	0	14.5		2489.13
P	42700T9CT81	WHEEL DISK AL 15X	Paid	1	4720.15	0	0	14.5		5404.57
P	IA260165120	3M Urethane Seamsealer Cartridge	Paid	5	1000	0	0	14.5		5725.00
P	62100T9DK20ZZ	PANEL COMP ROOF	Paid	1	15140	0	0	14.5		17335.30
P	63522T9AT00ZZ	STIFF L ROOF SIDE	Paid	1	639.13	0	0	14.5		731.80
P	34251S5A003	LENS	Paid	1	240.78	0	0	14.5		275.69
P	51350T9CT11	LWR ARM ASSY R FR	Paid	1	1521.74	0	0	14.5		1742.39
P	64520T9DK00ZZ	PLR COMP L FR INN	Paid	1	2022.11	0	0	14.5		2315.32
P	39160T9AT01	FEEDER ASSY ROOF	Paid	1	820	0	0	14.5		938.90
P	74306T9CD01	MLDG ASSY R ROOF	Paid	1	352.17	0	0	14.5		403.23
P	76837TM0T01	TUBE 1040	Paid	1	69.44	0	0	14.5		79.51
P	67865T9CD01	TAPE L RR DOOR SA	Paid	1	115.9	0	0	14.5		132.71
P	72311S5S003	CLIP DOOR WTHSTP	Paid	60	3.48	0	0	14.5		239.08
P	90135TY0J01	BOLT STRG JOINT YOKE	Paid	1	68.7	0	0	14.5		78.66
P	51211T9CT00	KNUCKLE R FR	Paid	1	2309.57	0	0	14.5		2644.46
P	51320T5A003	LINK COMP STABIF	Paid	1	445.3	0	0	14.5		509.87
P	77210T9DD00ZA	LID ASSY INST SIDE DR	Paid	1	68.7	0	0	14.5		78.66
P	72410T9CD01	MLDG ASSY R FR DO	Paid	1	616.52	0	0	14.5		705.92
P	72910T9CD01	MLDG ASSY R RR DO	Paid	1	418.7	0	0	14.5		479.41
P	75424T9CD00	GARN ASSY R RR PL	Paid	1	71	0	0	14.5		81.30
P	75701T9C000	EMBLEM H-MARK 77	Paid	1	160.87	0	0	14.5		184.20
P	71105T9DK00	GARN FR BUMPER LW	Paid	1	527.83	0	0	14.5		604.37
P	74100T9DK00	FENDER ASSY R FR	Paid	1	470	0	0	14.5		538.15
P	72365T9AT01	SUB SEAL L ROOF	Paid	1	542.61	0	0	14.5		621.29

P/L	Labor Code/Part#	Description	Issue Type	Qty	Job Value/RTLP	Disc /Item	Dis %	VAT/S.Tax %	OC/VAT (WCT)%	Amount(₹)
P	91505TM8003	CLIP.BUMPER	Paid	15	97.39	0	0	14.5		1672.67
P	90139SE0003	SCREW.TAPPING WASH 5	Paid	15	70.43	0	0	14.5		1209.64
P	91501TG2K01	CLIP.INN FENDER	Paid	15	69.02	0	0	14.5		1185.42
P	90114SE0000	SCREW.TAPPING WAS	Paid	8	86.24	0	0	14.5		789.96
P	77100T9DD20ZA	PANEL COMP.INST	Paid	1	7506.96	0	0	14.5		8595.47
P	77104T9AT01ZA	PANEL ASSY.AS MID	Paid	1	222.61	0	0	14.5		254.89
P	73127T9CK00	RUBBER.FR WSHLD D	Paid	1	28.36	0	0	14.5		32.47
P	73227TM0T00	RUBBER.WSHLD DAM C	Paid	1	111.65	0	0	14.5		127.84
P	76810T9DK01	NOZZLE ASSY WASHE	Paid	1	48.03	0	0	14.5		54.99
P	73127T9CK00	RUBBER.FR WSHLD D	Paid	4	28.36	0	0	14.5		129.89
P	76600T9AT01	ARM.WSHLD WIPER (Paid	1	490.2	0	0	14.5		561.28
P	76610T9AT01	ARM.WSHLD WIPER (Paid	1	507.9	0	0	14.5		581.55
P	75490T9CD00	GARN ASSY R.FR PL	Paid	1	146.09	0	0	14.5		167.27
P	74213T9CD01	FENDER COVER R	Paid	1	112.7	0	0	14.5		129.04
P	74223T9CD01	FENDER COVER L	Paid	1	112.7	0	0	14.5		129.04
P	44300T9CT51	BRG ASSY.FR HUB	Paid	1	1794.78	0	0	14.5		2055.02
P	42100T9CT12	BEAM ASSY.RR AXLE(200DRUM)	Paid	1	16946.09	0	0	14.5		19403.27
P	0827099901L	BRAKE FLUID DOT3 500ML	Paid	1	288.7	0	0	14.5		330.56
P	90701SX0003	CLIP.UPR ARM	Paid	1	79.61	0	0	14.5		91.15
P	90304SA5013	NUT.WHEEL MOUNT	Paid	2	180.87	0	0	14.5		414.19
P	9420120180	PIN COTTER 2.0MM	Paid	1	16.26	0	0	14.5		18.62
P	91604S5A003	GROMMET.BNT STAY	Paid	1	37.65	0	0	14.5		43.11
P	90672S5A003	ROD HOLDER	Paid	1	50.4	0	0	14.5		57.71
P	83414T9AT01ZC	BOOT COMP. C*NHIL*	Paid	1	1003.48	0	0	14.5		1148.98
P	44600T9CT00	HUB ASSY.FRONT	Paid	1	835.4	0	0	14.5		956.53
P	45255T5B000	SPLASH GUARD.FR B	Paid	1	120.87	0	0	14.5		138.40
P	38221SNAA31	BLADE FUSE.7.5A (LOW	Paid	2	18.7	0	0	14.5		42.82
P	73111T9CK01	SET.FR WSHLD GLAS	Paid	1	4260.8	0	0	14.5		4878.62
CARRYOUT DENTING										
L	RRFTFRBTMPR	R/RFT FRONT BUMPER	Paid	1	350	0	0	15		402.50
L	RRFTSHWGRL	R/RFT SHOW GRILL	Paid	1	75	0	0	15		86.25
L	RRFTBONNET	R/RFT BONNET	Paid	1	300	0	0	15		345.00
L	RRFTFWSGLS	R/RFT FRONT WIND SHIELD GLASS	Paid	1	1500	0	0	15		1725.00
L	RRFTLHFNDR	R/RFT LHS FENDER	Paid	1	300	0	0	15		345.00
L	RRFTRHFNDR	R/RFT RHS FENDER	Paid	1	300	0	0	15		345.00
L	RRFTFLDOR	R/RFT FRONT LH DOOR	Paid	1	400	0	0	15		460.00
L	RRFTFRDOR	R/RFT FRONT RH DOOR	Paid	1	400	0	0	15		460.00
L	RRFTRLDOR	R/RFT REAR LH DOOR	Paid	1	400	0	0	15		460.00
L	RRFTRRDOR	R/RFT REAR RH DOOR	Paid	1	400	0	0	15		460.00
L	RRFTRRWSGLS	R/RFT REAR W/SHLD GLASS	Paid	1	1200	0	0	15		1380.00
L	RRFTBOOTLID	R/RFT BOOT LID	Paid	1	400	0	0	15		460.00
L	RRFTRRBMPPR	R/RFT REAR BUMPER	Paid	1	300	0	0	15		345.00
L	RRFTDSHBRD	R/RFT DASHBOARD	Paid	1	2500	0	0	15		2875.00
L	RRFTLLMP	R/RFT TAIL LAMP (EACH)	Paid	2	150	0	0	15		172.50
L	RRFTTRIMS	R/RFT TRIMS	Paid	1	600	0	0	15		690.00
L	CRPTRRFIT	CARPET RENEW / REFIT	Paid	1	400	0	0	15		460.00

P/L	Labor Code/Part#	Description	Issue Type	Qty	Job Value/ RTLP	Disc /Item	Dis %	VAT/ S.Tax %	OC/VAT (WCT)%	Amount(₹)
L	RRFTWRHRS	R/RFT WIRING HARNES	Paid	1	800	0	0	15		920.00
L	RRFTROOFLNG	R/RFT ROOF LINING	Paid	1	700	0	0	15		805.00
L	RPLCRWHSG	REPLACE RH WHEEL HOUSING	Paid	1	1300	0	0	15		1495.00
L	RRFTFRSUSP	R/RFT FRONT SUSPENSION (1 SIDE)	Paid	1	1200	0	0	15		1380.00
L	RRFTWPMTLNK	R/RFT WIPER COWL / MOTOR LINKAGES	Paid	1	300	0	0	15		345.00
L	RRFTRFPNL	R/RFT ROOF PANNEL	Paid	1	3800	0	0	15		4370.00
L	RRFTRHQTRPNL	R/RFT RHS QTR PANEL	Paid	1	3200	0	0	15		3680.00
L	RPRLRNGBD	REPAIR LH RUNNING BOARD	Paid	1	1000	0	0	15		1150.00
L	RPRRRNGBD	REPAIR RH RUNNING BOARD	Paid	1	800	0	0	15		920.00
L	RPRLHQTRPNL	REPAIR LHS QTR PANEL	Paid	1	1500	0	0	15		1725.00
L	RRFTIBEAM	R/RFT I BEAM	Paid	1	100	0	0	15		115.00
L	RRFTHDLMP	R/RFT HEAD LAMP (EACH)	Paid	2	200	0	0	15		230.00
L	RPRBLKHD	REPAIR BULK HEAD	Paid	1	900	0	0	15		1035.00
L	RPRAPLR	REPAIR 'A' PILLAR	Paid	2	3000	0	0	15		3450.00
L	RPRRH CNTPLR	REPAIR RHS CENTRAL PILLAR	Paid	1	1000	0	0	15		1150.00
L	RPRLHCNTPLR	REPAIR LHS CENTRAL PILLAR	Paid	1	1000	0	0	15		1150.00
L	42700T9CT814211D4	Replace RIGHT FRONT DISC, WHEEL	Paid	1	255	105	0	15		172.50
L	WHALG	WHEEL ALIGNMENT	Paid	1	475	175	0	15		345.00
L	RPRRLDOR	REPAIR REAR LH DOOR	Paid	1	1300	0	0	15		1495.00
CARRYOUT PAINTING										
L	PNTFULLCAR	PAINT CHGS FULL CAR	Paid	1	40000	0	0	15	14.5	48840.00
CAR-O-LINNER CHARGES										
L	RPRCHGS	REPAIR CHARGES	Paid	1	2500	0	0	15		2875.00
REAR AXLE REPLACEMENT										
L	RRFTCHGS	R/RFT CHARGES	Paid	1	950	0	0	15		1092.50

Recommendations:

SUMMARY

Particulars	Amount(₹)
Total Parts Amt	260202.00
Total VAT Amt	37729.29
Additonal VAT	0.00
Total Labor Amt(PM/GR)	35975.00
Service Tax(PM/GR)(incl. SB & KK Cess)@ 15%	5396.25
Total Charges (PJ / CRS)	40000.00
Service Tax on 70% of (PJ/CRS)(incl. SB & KK Cess)@ 15%	4200.00
VAT(WCT) on 80% of (PJ/CRS)@ 14.5%	4640.00
Total Amount	388142.54
Net Amount	388142.54
Grand Total (Rounded - Off)	₹ 388143.00 (+ 0.46)
Amount in Words:	
Rupees Three Lakh Eighty Eight Thousand One Hundred Fourty Three Only	