

CLIMATE CONTROL

Fault finding – Fault finding chart

62C

ALP 11

Unpleasant odours in the passenger compartment

NOTES

None.

Check that the cabin filter is not blocked or damaged.

Is the fault still present?

NO

End of fault finding procedure.

YES

Check that the condensate drain pipe (water from the evaporator) is not blocked.

Is the fault still present?

NO

End of fault finding procedure.

YES

A

AFTER REPAIR

Carry out a full check with the **diagnostic tool**.