6/23/2014 Print

Subject: Re: Estimate for your Audi A6 MH 04 FZ 6876

From: Sahil Verma (sahil_verma@ymail.com)

To: taher.murgha@audimumbaisouth.net;

tejas.phadke@audimumbaisouth.net; kaustubh.koparde@audimumbaisouth.net;

rakesh.jagdale@audimumbaisouth.net; avnish.tripathi@audimumbaisouth.net;

Date: Monday, 16 December 2013, 17:49

Hi Taher,

I have made it very clear to Rakesh that I will authorise this repair only once it is confirmed as covered by the insurance company or through my Audi cover. I have purchased a Audi Platinum policy only to be covered in such situations and I am not willing to pay for these repairs from my pocket.

regards, Sahil

On Monday, 16 December 2013, 16:06, Taher Murgha taher.murgha@audimumbaisouth.net wrote: Dear Mr. Verma,

Greetings from Audi Mumbai South.

In continuation to your telecom with our Mr. Rakesh Jagdale, please find attached the estimate for the repairs on your Audi A6 MH 04 FZ 6876.

Please accord your approval for the necessary repairs allowing us to order the required spare parts.

With warm regards,

Taher Murgha Team Leader

Audi Mumbai South

M Square Automobile Pvt Ltd,

Workshop:- Plot No 31, Sew ri-Fort Road, Next to H.P.C.L Depot, Sew ri (East), Mumbai 400 015.

Showroom -Vasundhara Building 17 Bhulabhai Desai Road, Haji Ali, Next to Cadbury House, Mumbai - 400 026.

Mobile : +91 8879250383 Phone : +91 22 6612 8000 Fax : +91 22 6612 8099

Email: taher.murgha@audimumbaisouth.net

Website: www.audi-mumbaisouth.com



M Square Automobile Pvt. Ltd.

Plot No. 31, Sewri-Fort Road Next to H.P.C.L Depot, Sewri(E)

Mumbai, 400015

Phone No. Fax No.

022-66128000 022-66128099

DVAT Registration No.: 27680933975V P.A.N. No.

AAICM1315R 27680933975C

C.S.T. No.: Service Tax No.:

AAICM1315RSD001

MR OM PRAKASH VERMA

FLAT 301 PACIFIC HEIGHTS NR RIZVI COLLEGE BANDRA(W) MUMBAI, 400050 India



Service Quote

Customer No.

CU0696 SQ120542

Quote No. QuoteDate

16/12/13

Salesperson

1 Page

Make AUDI **Model Description**

A6 Sal, TDI 2.0 I4 130 A8M

Mileage 5,813

Service Advisor TEJAS PHADKE

License No.

Initial Registration

Sales Advisor

MH04FZ6876 **Engine Code**

WAUZAD4G4DY001451 **Labor Type**

Engine No.

Model Code

011643

4G2MTH

			011643		4G2MTH	
SNo.	Part / Labor No.	Description	Qty.	UoM	Unit Price	Amount
Labo	or Charges					
1	82451900	Fuel pump removed+reinstalled	40	Time Uni	18.00	720.00
2	23741960	High pressure pump removed+reinstalled	70	Time Uni	18.00	1,260.00
3	15241910	Toothed belt removed+reinstalled	250	Time Uni	18.00	4,500.00
1	23402010	Injector removed+reinstalled	130	Time Uni	18.00	2,340.00
5	20101950	Fuel tank removed+reinstalled	160	Time Uni	18.00	2,880.00
3	42051900	Rear axle removed+reinstalled	290	Time Uni	18.00	5,220.00
7	47010750	Brake system bled	30	Time Uni	18.00	540.00
8	20661900	Electric fuel pump removed+reinstalled	70	Time Uni	18.00	1,260.00
9	20030750	Fuel bled	10	Time Uni	18.00	180.00
10	99999000	GFF/Guided Functions	100	Time Uni	18.00	1,800.00
Part:	<u>s</u>					
1	03L130277J	INJECTION UNIT	4	Piece	29,917.34	119,669.36
2	WHT005302	ROUND SEAL	4	Piece	75.56	302.24
3	03L130089Q	FUEL DISTR	1	Piece	53,392.01	53,392.01
4	4G0919050A	FUEL UNIT	1	Piece	31,355.56	31,355.56
5	1J0919133B	WASHER	1	Piece	873.78	873.78
G 📁	03L130755AE	PUMP	1	Piece	130,612.46	130,612.46
7	N 91180301	FLAT HEAD MULTI-POINT	3	Piece	45.33	135.99
				Total of Labor Charges		20,700.00
				Total of Items		336,341.40
				Total (Excl. Tax) in INR		357,041.40
				Service Tax	@ 12.36 . %	2,558.52
				VAT	@ 12.5 %	42,042.68
					- 11 111	

We would require 20 Ltrs of fuel post completion of repairs

Total (Incl. Tax) in INR

401,642.60