

by
Praveen

Sheeram Guna

Ace of Harsha

Chandrababu

13/01/2010

ESTIMATE

HYUNDAI ACCENT

KA-04-P-6856

LABOUR

1	Front Bumper Replace	250.00	150
2	Front Grill Replace	50.00	—
3	Both Head Lamps r/r	100.00	80
4	Bonnet Assy Replace	200.00	150
5	RH Fender r/r	200.00	150
6	Radiator Assy r/r	250.00	150
7	A/C Condensor Assy r/r	350.00	200
8	A/C Gas Charging	1450.00	1200
9	Wheel Alignment	250.00	250

TINKERING

1	Member Hood Lock Repair	650.00	450
2	Radiator Support Frame Repair	1450.00	750
4	RH Fender Repair	750.00	500

PAINTING

1	Bonnet Painting	3000.00	2500
2	Front Bumper Painting	2500.00	2000
3	RH Fender Painting	2200.00	1800
4	Bulk Head Panel Painting	1500.00	X

13030

TOTAL LABOUR CHARGES Rs. 15,250.00

SPARES

1	Front Bumper Assy	2810.00	rep 400
2	Front Bumper Rail Assy	2395.00	rep 450
3	Front Bumper Bracket Assy RH	140.00	
4	Front Bumper Bracket Assy LH	140.00	

13/01/2010

ESTIMATE

HYUNDAI ACCENT

KA-04-P-6856

12004 ✓	5	Front Grill Assy	1,457.00 ✓
	6	Bonnet Assy	8,777.97 repair 15
	7	Bonnet Hinges (2.Nos)	674.00 ✓
	8	Bonnet Lock Assy	662.33 ✓
2800 ✓	9	Head Lamp Assy RH 2500 MA	3,250.00 ✓
	10	Head Lamp Assy LH	3,250.00 ✓
P350 ✓	11	Radiator Assy D. 5500	4,857.76 ✓
	12	Radiator Shroud With Fan Motor Assy	4,998.00 repair 350
9300 ✓	13	A/C Condensor Assy	9,284.51 ✓

TOTAL SPARES Rs. 43,310.00

TOTAL (LABOUR + SPARES) Rs. 58,560.00

(RUPEES FIFTY EIGHT THOUSAND FIVE HUNDRED SIXTY ONLY)

- Note:1) Supplimentary Estimate Will Be Given After Dismattling If Required
- 2) Vat On Spares Tax Will Be Extra.,

for SAI COLORIUM

[Signature]
MANAGER

12030
 2500
 2500
 12430