ŠKODA

History Card

A7

KA04MQ-1084



| | | | | | | | ~ |
|-------------|---------|---------------|-------|--------------|--|--|---|
| Vehicle | | | | | Registration KA04MQ-1084 | Engine CJS 101681 | Chassis TMBBDENE3FA007218 |
| Sold on | | | | | Selling Dealer | | Exterior |
| pened On | Dealer | Job# | Kms | Repair Type | Inv# Complaints Rcorded | Labour/Job Work done | Parts Issued |
| 06-May-2017 | VINAYAK | <u>077353</u> | 21042 | PAID SERVICE | 1612 THE RIGHT REAR SIDE DOOR HANDLE BAR IS N THE SUN VISOR HINGE IS BROKEN THE 'JERK' IS STILL THERE. I HAVE BEEN T THE CREAKING SOUND WHEN TURNING OVER THE THE WINDOW ON THE CO-DRIVER SEAT HAS ALS RATTLING SOUND ON THE FRONT-LEFT SIDE HA THE WHISTLING SOUND ON THE FRONT-RIGHT S 1) ERROR MESSAGE DISPLAYED ON THE SCREEN | Paid Service Charges CC Battery check CC PICKUP CHARGES CC GFF/Guided functions. CC Washing Cleaning Charges CC Interior Enrichment for Upholstry CC | 3372489 MAGNATEC PRO OE 5W40 208L W-OEM SHOULDERED HEX. NUT WIND SCREEN WASHER MISICELLNEOUS W-OEM SHIFT MECHANISM DUST AND POLLEN FILTER AIR FILTER W-OEM WINDOW REGULATOR W-OEM WINDOW REGULATOR W-OEM LOCK WASHER FILTER ELEMENT WITH GASKET W-OEM STICKER |
| 29-Dec-2016 | VINAYAK | 074580 | 17784 | RUNNING REPA | 7433 CHK FOR WHEN APPLYING BRAKE RPM GOES &CO CHK FOR GEAR DELAY SHIFTING IN 30 TO 40 CHK FOR NOISE NEAR STEERING | W-OEM Gearbox remove+reinstall WO W-OEM Engine complete remove reinstall WO W-OEM Front bumper remove+reinstall WO W-OEM Washing Cleaning Charges WO W-OEM fuel issued (petrol) WO | W-OEM 3372489 MAGNATEC PRO OE 5W40 208L W-OEM ROUND SEAL W-OEM ROUND SEAL W-OEM O-RING W-OEM SEAL RING W-OEM HEXAGON SOCKET HEAD BOLT W-OEM HEXAGON SOCKET FLAT W-OEM BOLT, WITH POLYGON SOCKET HD. W-OEM BOLT, HEX. HD. WITH SHOULDER W-OEM BOLT, HEX. HD. WITH SHOULDER W-OEM HEXAGON SOCKET FLAT W-OEM COOLANT ADDITIVE W-OEM WATER HOSE W-OEM GASKET W-OEM FUEL LINE W-OEM FUEL LINE W-OEM FUEL LINE W-OEM FUEL LINE W-OEM FLYWHEEL W-OEM GASKET W-OEM LONG BLOCK W-OEM NEEDLE BEARING - |
| 28-Nov-2016 | VINAYAK | <u>073817</u> | 17061 | SERVICE CAMP | 5714 VEHICLE TOWED TO WORK SHOP CHK VEHICLE NOT STARTING | W-OEM Battery replaced WO Wheel alignment CC Wheel balancing – (4 wheels) CC W-OEM Front electric window lifter replacementWO W-OEM Mechatronics remove+reinstall WO W-OEM Multiple clutches remove+reinstall WO Washing Cleaning Charges CC Interior Enrichment for Upholstry CC | W-OEM ADJUSTING WASHER W-OEM BOLT, WITH POLYGON SOCKET HD. W-OEM WINDOW REGULATOR W-OEM MECHATRONIC WITH SOFTWARE W-OEM REPAIR KIT FOR W-OEM ADJUSTING WASHER W-OEM ADJUSTING WASHER W-OEM NEEDLE BEARING - W-OEM ROUND HD. SCREW W-OEM BATTERY WITH CHARGE STATE |
|)2-Nov-2016 | VINAYAK | <u>073164</u> | 16659 | RUNNING REPA | 5169 CHK RATTLING SOUND FROM LEFT SIDE CHK WHISTLING SOUND ON THE FRONT RH SIDE CHK SINGLE JERK WHEN DRIVEN AFTER AGAP O HOT AIR BLOWING OUT OF THE A/C DUTCTWHIL CHK FOR A/C COOLING NOT EFFECTIVE CHK FOR RH FRONT POWER WINDOW STRUKS WHI DO W/A W/B | petrol CC | W-OEM SPECIAL LUBRICANT |

| 22-Aug-2016 VINAYAK | <u>071631</u> 14315 | RUNNING REPA | 3326 CHK FOR RATTLING SOUND FROM FRONT L/H SI CHK FOR SUN ROOF NOISE CHK FOR JERK WHEN DRIVEN AFTER A GAP OF CHK FOR WHISTLING SOUND ON RH SIDE | GFF/Guided functions. CC W-OEM Brake cleaning WO | |
|---------------------|---------------------|--------------|--|--|---|
| 01-Jul-2016 VINAYAK | <u>019467</u> 13008 | RUNNING REPA | 1433 CHECK RATTLING NOISE FROM LH SIDE, ON POT | | |
| 21-Jun-2016 VINAYAK | <u>019318</u> 12704 | ACCESSORY FI | 1146 PROVIDE ACCESSORIES (BOOT MATE , DOOR SE | Mud flaps replacement CC Inspection Charges (General Check Up) CC | MOBILE PHONE HOLDER SMARTPHONE DECORATIVE TRIM FOR LID Car Cover Polyester Silver New Octavia |

PRUDHVI at BNG02 from VINAYAK, Saturday, July 01, 2017 12:26 CRM-WebDMS [IP: 1.23.211.190]

ŠKODA

History Card

A7

KA04MQ-1084



| Vehicle | A7 - | | | | Registration KA04MQ-1084 | Engine CJS 101681 | Chassis TMBBDENE3FA007218 |
|-------------|---------|---------------|-------|--------------|--|---|--|
| Sold on | | | | | Selling Dealer | | Exterior |
| Opened On | Dealer | Job# | Kms | Repair Type | Inv# Complaints Rcorded | Labour/Job Work done | Parts Issued |
| | | | | | | | FRONT MUD FLAPS OCTAVIA Door sill covers Front - Alu silver Rubber boot mat CONNECTING CABEL FOR JACK 3,5 MM - MDI |
| 09-Jun-2016 | VINAYAK | <u>019144</u> | 12325 | PAID SERVICE | 985 DO FIRST FREE SERVICE (E/O O/F F/F) DO W/B W/A W/R CHECK ENGINE NOISE WHILE ACCELARATING | 1st Free Service CC Wheel alignment CC Wheel balancing (per wheel) CC Wheel balancing (per wheel) CC Wheel balancing (per wheel) CC Wheel balancing (per wheel) CC | 3372489 MAGNATEC PRO OE 5W40 208L Lead Weight 80GM WIND SCREEN WASHER FEVI QUICK MISICELLNEOUS DUST AND POLLEN FILTER AIR FILTER FILTER ELEMENT WITH GASKET |
| 30-Nov-2015 | VINAYAK | <u>016721</u> | 6868 | FREE CHECKUP | 3436 DO FIRST FREE CHECK UP DO A/C NEUTRALIZATION DO FULL WASHING DO INTERIOR FOAM CLEANING CHECK WHISELING NOISE WHILE STARTING | Washing Cleaning CC free check up done CC interior foam cleaning done CC | |