

Tuesday,11,September,2012,13:54:20:23247

VCDS Version: Release 11.11.4 (x64)

Data version: 20120807

Chassis Type: 7N0

Scan: 01 03 08 09 10 15 16 17 19 22 25 42 44 46 52 56 62 72

VIN: TMBMDF5L4BA701424

01-Engine -- Status: OK 0000

03-ABS Brakes -- Status: OK 0000

04-Steering Angle -- Status: OK 0000

08-Auto HVAC -- Status: OK 0000

09-Cent. Elect. -- Status: OK 0000

10-Park/Steer Assist -- Status: OK 0000

15-Airbags -- Status: OK 0000

16-Steering wheel -- Status: OK 0000

17-Instruments -- Status: OK 0000

19-CAN Gateway -- Status: OK 0000

22-AWD -- Status: OK 0000

25-Immobilizer -- Status: OK 0000

42-Door Elect, Driver -- Status: OK 0000

44-Steering Assist -- Status: OK 0000

46-Central Conv. -- Status: OK 0000

52-Door Elect, Pass. -- Status: OK 0000

56-Radio -- Status: OK 0000

62-Door, Rear Left -- Status: OK 0000

72-Door, Rear Right -- Status: OK 0000

Address 01: Engine (J623-CLCB) Labels: 03L-906-018-CFF.clb

Part No SW: 03L 906 018 EK HW: 03L 906 018 BR

Component: R4 2,0L EDC H23 9482

Revision: 42H23--- Serial number:

Coding: 00190012040700080000

Shop #: WSC 02700 940 183044

ASAM Dataset: EV_ECM20TDI01103L906018EK 003007

ROD: EV_ECM20TDI01103L906018EK.rod

VCID: 77FD54D5CE978BA010F

No fault code found.

Readiness: 0 0 0 0 0

Address 03: ABS Brakes (J104) Labels: 1K0-907-379-60EC1F.clb

Part No SW: 1K0 907 379 BE HW: 1K0 907 379 BE

Component: ESP MK60EC1 H31 0108

Revision: 00H31001

Coding: 933F400E092201FBC90F02E6901D808A310000

Shop #: WSC 73430 790 00999

VCID: 76E359D1C19DF2A80B9

No fault code found.

Address 08: Auto HVAC (J255) Labels: 5K0-907-044.clb

Part No SW: 3T0 907 044 BD HW: 3T0 907 044 BD

Component: Climatronic H16 0402

Revision: 00006001

Coding: 0000001002

Shop #: WSC 73430 790 00999

ASAM Dataset: EV_Climatronic A01010

ROD: EV_Climatronic_SK35.rod

VCID: 75E15EDDD49BF9B0023

No fault code found.

Address 09: Cent. Elect. (J519) Labels: 1K0-937-08x-09.clb

Part No SW: 1K0 937 086 H HW: 1K0 937 086 H

Component: BCM PQ35 M 103 0615

Revision: 00103 AE

Coding: 48000AB8E00508C040080080110081E4410000AE526D81605C8140000040

Shop #: WSC 73430 790 00074

VCID: 35619EDD9C1BB9B0C23

Subsystem 1 - Part No: 5L2 955 119 A

Component: SK356 26 0604

Coding: 00F7B5

Subsystem 2 - Part No: 1K0 955 559 AH Labels: 1K0-955-559-AG.CLB

Component: RLS 190411 05 54 0403

Coding: 0730ED

No fault code found.

Address 10: Park/Steer Assist (J446) Labels: 1Z0-919-475-V2.clb

Part No SW: 1Z0 919 475 E HW: 7N0 919 475

Component: PARKHILFE 8K H06 0005

Revision: --H06--- Serial number: 28291108759004

Coding: 108006

Shop #: WSC 33361 790 00999

ASAM Dataset: EV_EPHVA18SKxxx0000 001001

ROD: EV_EPHVA18SKxxx0000_SK35.rod

VCID: 4385F005CACF17007C7

No fault code found.

Address 15: Airbags (J234) Labels: 5K0-959-655.clb

Part No SW: 5C0 959 655 C HW: 5C0 959 655 C

Component: AirbagVW10 013 0613

Serial number: 003G6RA1DHT-

Coding: 0000544A

Shop #: WSC 33361 790 00999

ASAM Dataset: EV_AirbaVW10SMEVW360 A01014

ROD: EV_AirbaVW10SMEVW360_SK35.rod

VCID: 326BA5C16575AE88E71

Crash sensor for side airbag; driver side:

Subsystem 1 - Part No SW: 5K0 959 354 HW: 5K0 959 354

Component: S.Sens.Fahr.V H01 ----

Serial number: 3572MSME4853615DZZZ

Crash sensor for side airbag; passenger side:

Subsystem 2 - Part No SW: 5K0 959 354 HW: 5K0 959 354

Component: S.Sens.Beif.V H01 ----

Serial number: 3582MSME682E555EZZZA

Crash sensor for side airbag; rear driver side:

Component: S.Sens.Fahr.H --- ----

Serial number: 3512QSME78380354ZZZT

Crash sensor for side airbag; rear passenger side:

Component: S.Sens.Beif.H --- ----

Serial number: 3522QSME7A170354ZZZT

No fault code found.

Address 16: Steering wheel (J527) Labels: 5K0-953-569.clb

Part No SW: 5K0 953 521 BM HW: 5K0 953 569 D

Component: LENKS.MODUL 014 0140

Revision: FF010040 Serial number: 20110428100244

Coding: 1082040000

Shop #: WSC 33361 790 00999

ASAM Dataset: EV_SMLSNGVOLWSXS A01004

ROD: EV_SMLSNGVOLWSXS_SK35.rod

VCID: 78FF57E9C38984D8195

Multifunction steering wheel control module:

Subsystem 1 - Part No SW: 3T0 959 537 HW: 3T0 959 537 Labels: 3C8-959-537.CLB

Component: E221__MFL-URO H07 0012

Coding: 800000

No fault code found.

Address 17: Instruments (J285) Labels: 5K0-920-xxx-17.clb

Part No SW: 5L0 920 840 H HW: 5L0 920 840 H

Component: KOMBI H21 0420

Serial number: 000000000000000

Coding: 120A00

Shop #: WSC 73430 031 00999

ASAM Dataset: EV_Kombi_UDS_VDD_RM09 A04089

ROD: EV_Kombi_UDS_VDD_RM09_SK35.rod

VCID: 306FAFC96B799C98915

No fault code found.

Address 19: CAN Gateway (J533) Labels: 7N0-907-530-V2.clb

Part No SW: 7N0 907 530 C HW: 1K0 907 951

Component: J533 Gateway H37 0614

Revision: H37 Serial number: 120411F1001552

Coding: 356303

Shop #: WSC 73430 790 00074

VCID: 306FAFC963799C98915

No fault code found.

Address 22: AWD Labels: Redir Fail!

Part No SW: 0BR 907 554 B HW: 0BR 907 554 B

Component: Haldex 4Motion 3017

Coding: 0000005

Shop #: WSC 00000 000 00000

VCID: 4487F31907C1103845D

No fault code found.

Address 25: Immobilizer (J334) Labels: 5K0-920-xxx-25.clb

Part No SW: 5K0 953 234 HW: 5K0 953 234

Component: IMMO H21 0420

Serial number: 00000000000000

Coding: 000000

Shop #: WSC 00000 000 00000

ASAM Dataset: EV_Immo_UDS_VDD_RM09 A03008

ROD: EV_Immo_UDS_VDD_RM09_SK35.rod

VCID: EADBFDA10D25A6481F1

No fault code found.

Address 42: Door Elect, Driver (J386) Labels: 7N0-959-793.clb

Part No SW: 7N0 959 793 E HW: 7N0 959 793 A

Component: TSG FA H04 0400

Revision: Serial number: 0000114561845

Coding: 011502208001231004

Shop #: WSC 73430 790 00999

VCID: 4487F319C7C1103845D

No fault code found.

Address 44: Steering Assist Labels: 1Kx-909-14x-44.clb

Part No: 1K0 909 144 M

Component: EPS_ZFLS Kl. 70 3201

Revision: 00H20000

Shop #: WSC 73430 790 00074

VCID: 3467A3D95761A0B8F5D

No fault code found.

Address 52: Door Elect, Pass. (J387) Labels: 7N0-959-792.clb

Part No SW: 7N0 959 792 E HW: 7N0 959 792 A

Component: TSG BF H04 0400

Revision: Serial number: 0000012474230

Coding: 011500208001231004

Shop #: WSC 73430 790 00999

VCID: 4385F005C2CF17007C7

No fault code found.

Address 56: Radio (J503) Labels: 5M0-035-1xx-56.clb

Part No SW: 1Z0 035 156 G HW: 1Z0 035 156 G

Component: BOLERO 015 0029

Revision: -----29S Serial number: SKZ4Z3L1121116

Coding: 0D0004000001

Shop #: WSC 73430 790 00999

VCID: 366399D1811DB2A8CB9

No fault code found.

Address 62: Door, Rear Left (J388) Labels: 7N0-959-795.clb

Part No SW: 7N0 959 795 D HW: 7N0 959 795

Component: TSG HL H03 0400

Revision: Serial number: 0000114627701

Coding: 010000200001531004

Shop #: WSC 73430 790 00999

VCID: 4581EE1DCCFB2930523

No fault code found.

Address 72: Door, Rear Right (J389) Labels: 7N0-959-795.clb

Part No SW: 7N0 959 795 D HW: 7N0 959 795

Component: TSG HR H03 0400

Revision: Serial number: 0000114840695

Coding: 010000200001531004

Shop #: WSC 73430 790 00999

VCID: 4581EE1DCCFB2930523

No fault code found.

End -----