



SUZUKI MARUTI SWIFT - 2 AIRBAGS

			Tested at	16.23	max. 17.00 max. 49.0 Bodyshell integr	00 Child
ADULT OCCUPANT PROTECTION			CAR DETAILS			
		GOOD ADEQUATE MARGINAL WEAK POOR	TES	TED MODEL	SUZUKI MAR RHD	UT SWIFT,
				BODY TYPE	5 DOOR HAT	СНВАСК
			CRASH T	EST WEIGHT	KG 1079	
			YEAR OF P	UBLICATION	2018	
FRONT PASSENGER	DRIVER					
CHILD RESTRAINTS						
	CHILD RESTRAINT	HEAD / CHEST		CRS TYPE	ADJUST	POSITION
18 MONTH OLD CHILD	BRITAX DUO PLUS	POOR / POOR		1	ISOFIX/TT	FWF
3 YEAR OLD CHILD	BRITAX DUO PLUS	PROTECTED / VU	LNERABLE	1	ISOFIX/TT	FWF
SAFETY EQUIPMENT						
FRONT SEATBELT PRETENSIONERS YES		SIDE BODY AI	RBAGS NO	SBR		NO
DRIVER FRONTAL AIRBAG YES		SIDE HEAD AI	RBAGS NO	ISO	FIX ANCHORAG	ies yes

ADULT OCCUPANT

FRONT PASSENGER FRONTAL AIRBAG YES

The protection offered to the driver and passenger head and neck was good. Driver chest showed weak protection while passenger chest showed adequate protection. Driver's knees showed marginal protection and passengers' knees good and adequate protection as they could impact with dangerous structures behind the dashboard supported by the Tranfasciatube. The bodyshellwas rated as unstable and it was not capable of withstanding further loadings. The car offers standard SBR for driver but it does not meet the minimum requirements.

DRIVER KNEE AIRBAG NO

ABS (4 CHANNEL)

YES

CHILD OCCUPANT

The child seat for the 3 year old was installed FWF with ISOFIX and top tether and was able to prevent excessive forward movement during the impact while it offered good protection and marginal protection to the chest. The 18 month old CRs was installed with ISOFIX and top tether forward facing which explains the loss of head points, it showed poor protection for the head and chest. The recommended CRSs did not show incompatibility. The vehicle offers standard ISOFIX and top tether anchorages in the 2 outboard rear seats and does not offer 3 point belts in all seating positions.