



APPLE AUTO PVT. LTD.,

#102/1, Shantha Kumar Layout, Outer Ring Road, B. Narayana Pura,
Whitefield, Bangalore - 560016
Ph. No. : 080-28514545 / 28512022 / 28512033



Volkswagen Whitefield

RECEIPT

No. **128**

Date: 8-10-15

RECEIVED with thanks from Rakesh Nagavarapu KA 03 MR 3890

the sum of Rupees Forteen thousand two ninety four only.


Cash/Cheque/DD in full/part payment towards Service

Financed by: Bank / Swipe Branch

Pay Order / Cheque / DD No. 4961

₹ 14294/-
(Cheque subject to realization)

* Price applicable at the time of delivery



VW
Apple Auto Pvt.Ltd

102/1, Outer Ring Rd,
B.Narayanpur, Whitefield, BANGALORE, 560016

Phone No.

080-6060 6611/14

Fax No.

E-Mail

service@vw-appleauto.co.in

CIN No.



VAT R.C No. : 29850630869 W.E.F.
C.S.T.R.C No. : W.E.F.
Ser. Tax. No. : AAJCA7861MSD001
PAN : AAJCA7861M

Tax Invoice

Repair Order No. SO177464
Repair Order Date 06 - Oct - 15
Customer Name RAKESH NAGAVARAPU
Customer Add. 1ST FLOOR, 2ND DOOR
NO 269, 6TH MAIN
BANGALORE, 560076
India

Next Due Date

Invoice No. SIP187442
Invoice Date 08 - Oct - 15
Regn. No. KA03MR3890
VIN WVWL12607DT026676
Model Polo Highline 1.2L CR M/T
Kms In 45,172
Kms Out 45,176
Service Advisor JHONY JOSEPH
S.A. Mob. No. 9900010726

Demanded Repair (Customer Voice)

- 1
- 2 DO 3RD SERVICE===54739
- 3 CHECK ALL AC VENTS
- 4 CHECK ALL SHOCKS MAKING ROUGH NOISE
- 5 REFIX FT RH BUMPER

Labor Details

S. No.	Description	Labor Code	Cate- gory	Qty.	Unit Price	Customer Share %	Amount	Ser.Tax (14%)	Amount incl. Tax
1	POLO DIESEL 45000 MAI	99PO45KD	Paid	428	4.50	100.00	1,926.00	269.64	2,195.64
2	Exterior clean	00000018	Paid	219	4.50	100.00	985.50	137.97	1,123.47
3	Air vent centre removed+r	85531950	Paid	25	4.50	100.00	112.50	15.75	128.25
							3,024.00	423.36	3,447.36

Parts Details

S. No.	Description	Part No.	Cate- gory	Qty.	Unit Price	Customer Share %	Amount	VAT %	VAT Amount	Amount incl. Tax
1	Castrol Magnetic professi	LP-CMPOE5W40	Paid	4.3	820.96	100.00	3,530.13	14.50	511.87	4,042.00
2	FILTER ELEMENT WITH	03P115562	Paid	1	310.04	100.00	310.04	14.50	44.96	355.00
3	PLUG WITH	N 90813202	Paid	1	145.85	100.00	145.85	14.50	21.15	167.00
4	AIR FILTER	6RF129620	Paid	1	342.36	100.00	342.36	14.50	49.64	392.00
5	FUEL FILTER	6RF127400A	Paid	1	1,124.02	100.00	1,124.02	14.50	162.98	1,287.00
6	DUST AND POLLEN FILT	6R0820367	Paid	1	579.91	100.00	579.91	14.50	84.09	664.00
7	WINDSHIELD CLEANER	G 052164M1	Paid	1	282.97	100.00	282.97	14.50	41.03	324.00
8	AIR VENT	6R0819703AGVA	Paid	1	793.01	100.00	793.01	14.50	114.99	908.00
9	AIR VENT	6R0819704AGVA	Paid	1	793.01	100.00	793.01	14.50	114.99	908.00
10	AIR VENT	6R0819728BCVA	Paid	1	1,572.05	100.00	1,572.05	14.50	227.95	1,800.00
							9,473.35		1,373.65	10,847.00

Total Parts and Labor 14,294.00

Rupees :

FOURTEEN THOUSAND TWO HUNDRED NINETY FOUR RUPEES AND ZERO PAISA ONLY