

MADHUS ENTERPRISES
 NO.35/5, LANGFORD ROAD (NEAR DOUBLE ROAD
 CIRCLE)
 BANGALORE-560026

Customer

Ph.41519430/50
 ALIGNMENT CHECKUP WITHIN 1000 Kms OR 15 DAYS
 WHICH EVER IS EARLIER

Vehicle Ident no.

Repair order no.
 R006948

Technician
 RB

Date
 23.11.16

Odometer reading: km/miles
 76078

License plate no.
 KA 40 P 600

First reg. date

Model
 TOYOTA QUALIS

Complaints or reason for alignment check

		Before	Target Data		Actual
Rear axle	Camber	left	-0°06'		-0°03'
		right	-0°01'		-0°02'
		cross	-0°04'	0°00'	-0°01'
	Toe	left	0°09'		0°07'
		right	-0°11'		-0°06'
		total	-0°01'		0°01'
Geometrical driving axis		0°10'	0°00'	0°07'	
	Camber	left	-0°17'	0°35' +/-0°30'	0°35'
		right	1°41'		0°36'
		cross	-1°58'	0°00'	-0°01'
Front axle	Caster	left	-0°35'	0°50' +/-0°30'	1°02'
		right	2°11'		1°12'
		cross	-2°48'	0°00'	-0°10'
	SAI	left		12°20' +/-2°00'	
		right			
		cross		0°00'	
Track differential angle		left			
		right			
Toe	left	0°08'	0°15' +/-0°06'	0°16'	
	right	0°13'		0°17'	
	total	0°21'	0°30' +/-0°12'	0°33'	
Setback			0°00'		
Max steering lock	left steer	left			
		right			
	right steer	left			
		right			