SR	PART NO. DESCRIPTION	Insurance(Y/N)	QTY	RATE	TAX	AMOUNT
Billa	ble					
1	1145962		1.000	55.50	8.05	55.50
	GASKET					
	1216529 WASH FILLID BOLIGH		1.000	54.05	7.84	54.05
3	WASH FLUID POUCH 1530536		1.000	333.37	48.34	333.37
	OIL FILTER- DV4		1.000	000.07	40.04	333.37
	ENG OIL 5W30 ENGINE OIL 5W30		4.610	278.41	186.10	1,283.47
	Labour And Ser	vices				
Billa	ble					
	3001AF		1.000	261.00	32.26	261.00
	Caster, Camber, Toe-in - C	heck - Front				
	99P		1.000	.00	.00	.00
		s completed as per the Vehicle Report Card				
	GBATT		1.000	.00	.00	.00
	Battery condition (Green) -	No action required				
	GBK		1.000	.00	.00	.00
	Brake Lining (Green) - No a	action required	1.000	.00	00	.00
	Brake system (including line	oe hocos and narking			.00	.00
3	GCOOL	es, noses and parking	1.000	.00	.00	.00
	Engine cooling system, rad	iator, hoses and clam			.00	
7	GE-010		1.000	100.00	12.36	100.00
	Consumbales					
3	GEXH		1.000	.00	.00	.00
	Exhaust system (leaks, dar	nage, loose parts) (G				
	GTYRE		1.000	.00	.00	.00
	Tyre related issues (Green)	) - No action required				
I B	ler Paid					
	A10510000	Di I	1.000	.00	.00	.00
	10000 Km Service - Durato	ord Diesel				
		Labour Total :				
		Service Tax + Edu.cess @ 12.36%				
			VALUE ADDED TAX @ 14.5%			