

TYRE ENVIRO
27th MAIN, HSR LAYOUT
NEAR HSR POLICE STATION
BANGALORE
PH 9845 18844

Customer **punnyabrata**
(H)7411617004

Vehicle ident no. _____ Repair order no. **R004138**

Technician **naga** Date **24.3.14**

License plate no. **wb 02 X 2109** First reg. date _____ Model **Maruti-Suzuki : Alto** Odometer reading: km/miles **56252**

Complaints or reason for alignment check _____

		Before	Target Data	Actual	
Rear axle	Camber	left	-0°09'	-0°09'	
		right	-0°22'	-0°21'	
		cross	0°13'	0°00'	0°13'
	Toe	left	0°22'		0°21'
		right	0°00'		0°01'
		total	0°22'		0°22'
Geometrical driving axis		0°11'	0°00'	0°10'	
Front axle	Camber	left	-1°26'	-1°26'	
		right	-0°54'	0°10' +/-1°00'	-0°57'
		cross	-0°32'	0°00'	-0°29'
	Caster	left	1°16'	3°35' +/-1°00'	1°16'
		right	3°27'		3°27'
		cross	-2°11'	0°00'	-2°11'
SAI	left	13°13'	11°40' +/-1°00'	13°13'	
	right	12°30'		12°32'	
	cross	0°43'	0°00'	0°40'	
Track differential angle		left			
		right			
Toe	left	-0°13'	0°00' +/-0°02'	0°01'	
	right	-0°03'		0°00'	
	total	-0°16'	0°00' +/-0°05'	0°01'	
Setback			0°00'		
Max steering lock	left steer	left	38°00' +/-3°00'		
		right	33°00' +/-3°00'		
	right steer	left	33°00' +/-3°00'		
		right	38°00' +/-3°00'		

WinAlign V11.1 BE33 International 2011.01.17.0201